



DEPARTMENT OF
WATER RESOURCES

UPPER SACRAMENTO AREA *Fact Sheet* Site 182.0

Emergency Levee Repairs Fall 2006

Location

River: Sacramento

River Mile: 182.0

Longitude/Latitude:

N39.606861

W121.994536

Nearest Communities:

Hamilton City/

Chico/Willows

County: Glenn

Bank: Right



Length of Repair

5,000 feet (approximate)*

Repair Type

Rock material

Lead Agency

Department of
Water Resources

* Length of repair may change.



For further information,
please contact:

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov